

## AIR FLOW METER PCE-HWA 30



### Product Included

- Equipment
- Micro USB cable
- Transport case
- Instruction manual



### Features

- The meter measures the flow velocity according to the hot wire principle.
- The measuring range of the hot wire anemometer is between 0 ... 30.0 m/s
- Easy to use
- low cost but worthy

### Technical Data

#### Velocity :

**Measuring range :** 0...30 m/s

**Accuracy :**  $\pm 3\%$   $\pm 0.1$  m/s of measured value

**Resolution :** 0.01 m/s

**Unit :** m/s, ft/min, km/h, MPH, knots

#### Temperature :

**Measuring range :** 0...45°C

**Accuracy :**  $\pm 1.0$  °C

**Resolution :** 0.1 °C

#### Flow rate :

**Measuring range :** 0...999,990 m<sup>3</sup>/min (depend on tube size)

**Resolution :** 0.001 m<sup>3</sup>/min

**Unit :** CFM, CMM

**Operating temperature :** 0...50°C

**Operating humidity :** 40...80 %RH (non-condensing)

**Probe length :** 740 mm

**Probe diameter :**  $\varnothing 0.8$  ... 1.2 mm

**Dimension :** 70 x 194 x 35 mm

**Internal memory :** 960 measured values

**Battery voltage :** 3.7 V battery

**Weight :** 400g



[www.omi.co.th](http://www.omi.co.th)

**Omega Measuring Instrument Co., Ltd.**

Tel : 02-105-4676

Fax : 02-903-0080 ext. 6867

Email : [info@omi.co.th](mailto:info@omi.co.th)

Line : @omith